

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Sung-Chol YANG

Application No.: 10/807,344

Confirmation No.: 3492

Filed: March 24, 2004

U.S. Patent No.: 6,972,522

Issued: December 6, 2005

For:

MAGNETRON

ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Batch No.:

Certificate

APR 0 6 2006

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

Gene M. Garner, II Registration No. 34,172

04/04/2006 MBEYENE2 0000W103 6972522

100.00 OP

Date:

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

APR - 7 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,972,522

DATED: December 6, 2005

INVENTOR(S): Sung-Chol YANG

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 6, line 39, Claim 7, replace "pair" with --pair of--, therefor;

MAILING ADDRESS OF SENDER: STAAS & HALSEY 1201 New York Avenue, N.W. 7th Floor Washington, DC 20005 PATENT NO. 6,972,522

No. of add'l copies @ 304 per page